BUILDING CERTIFICATE

Sapper(Rangas), Distt. Hamirpur (H.P) was inspected by the concerned Junior Engineer. The building has neither been designed nor constructed by this department. No earthquake resistant norms have been adopted for this building. No structural drawings approved by the competent Government Agency have been produced. The structure is a Non Engineering structure. Hence the structural safety of this building can not be ensured specially from earthquake point of view. The year of construction of this building is also not known. This department will not be responsible for any type of loss of life and property etc. if this structure fails under any circumstances. However as per visual inspection, the building appears to be safe at present only. This certificate is valid for academic session 2018-2019.

Junior Engineer, P Section RANGAS Mu

Assistant Engineer, Sub-Division, HP.PWD

Nadaun

8.01.2018

Hamirpur Division

1/5